

All funds received by customer were applied to the project.




Figure 1 Screenshot of my correspondence with the Missouri Attorney General




Figure 2 Screenshot of my correspondence with the Missouri Attorney General stating my position




Figure 3 One of two images showing my final communications with the customer




Figure 4 Image showing final communication with the customer



*Figure 5 Image of pump truck preparing for concrete*



*Figure 6 Image of second story concrete slab prior to finishing*



*Figure 7 Image of second story slab in progress*



*Figure 8 image showing vertical rebar*



Figure 9 Image showing second story slab in progress



*Figure 10 Image showing excessive tied rebar in place prior to pour*



*Figure 11 Image showing more rebar than the engineer called for*



Figure 12 Image showing excessive rebar down main support channel



*Figure 13 Image showing second story preparation prior to slab pour*



Figure 14 Image showing second story prep prior to slab pour

