

Photos of the Smith Pool Under Construction

All funds provided by the customer went directly into the project.



Figure 1 Picture of the pool as its nearing completion. One of the final two photos taken just prior to the unexpected confrontation with Emily Smith.



Figure 2 Picture of the pool as its nearing completion. One of the final two photos taken just prior to the unexpected confrontation with Emily Smith.



Figure 3 Photo showing completed interior and nearing completion of retaining wall



Figure 4 Photo showing completed interior and nearing completion of retaining wall



Figure 5 Photo showing solid filled retaining wall with 6" of reinforced concrete



Figure 6 Photo showing interior Hard Shell Liner nearing completion



Figure 7 Photo showing workers pumping concrete into the wall forms



Figure 8 Photo showing excavation just prior to hitting solid granite shelf rock



Figure 9 Photo showing drain pipes secured in place and exposed shelf rock



Figure 10 Photo showing #5 rebar 12" on center in deep end



Figure 11 Photo Showing #8 copper bonding wire properly secured to tied rebar



Figure 12 Photo showing cracked concrete. Photo was taken prior to construction. This photo was taken as a precautionary measure just in case the customer accused anyone of damaging the concrete. This shows the customer was willing to lie in her court complaint



Figure 13 Photo showing cracked concrete. Photo was taken prior to construction. This photo was taken as a precautionary measure just in case the customer accused anyone of damaging the concrete. This shows the customer was willing to lie in her court complaint